

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

http://sitedevelopment.geoneering.com/e/signup.html

# BRYANT

CONSULTANTS

REGISTRATION [LOG IN]  
[GEONEERING HOME PAGE]

Usage of this system is restricted to those individuals and companies approved by Bryant Consultants, Inc. If you would like an account, please fill in the form below, indicate your acceptance of the User Agreement, and click "Submit".

Name:  (First)  (Last)

Company Name:

Address:

City, State, ZIP:

Company Web Site:  http://

Your Email:

Phone Number:

User Agreement: ☐

Bryant Consultants, Inc., and Earthsystems Technologies are all in and of the same company. For the purposes of this User Agreement and Privacy Statement, Bryant Consultants, Inc. will represent by both entities.

Scope  
This Terms of Use of Earthsystems Technologies, Inc. Content ("Agreement") is applicable to any content that is provided by Earthsystems Technologies, Inc. that you access by virtue of the Web site from which you are accessing this

FIG 1  
Registration Screen

18634.0111




FIG. 2  
Login Screen




FIG 3  
Project Selection Screen



Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

Address: http://sitedevelopment.geoneering.com/e/mt\_projects.html?mode=edit&projectID=568&stateInfo=eLHcEjRac8BdaJYq8833j7

# BRYANT

CONSULTANTS

EDIT PROJECT

[PROJECT ADMIN] [CONTACT ADMIN]  
[GEONEERING] [GEONEERING OVERVIEW] [LOG OUT]

Project Name: Providence Phase I  
Start Date: 11/12/02  
End Date: 11/12/02

Save project Back to Project Admin Work on this project

Audio info  
Created: 11/12/02 11:58:50 AM  
Updated:

510 514 512 506 504  
306 308

FIG 5  
Edit project screen




FIG 6  
Contact administration  
screen




FIG 7  
Edit contact screen

306 306

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

http://sitedevelopment.geoneering.com/e/project.html

# BRYANT CONSULTANTS

Contact Administration [PROJECT ADMIN] [GEONEERING] [GEONEERING OVERVIEW] [LOG OUT]

Project: Swampland Estates Phase I

General Contacts | Project Contacts

This is a list of contacts that apply to the project: "Swampland Estates Phase I"  
 You should select a contact for each role. If you need to define a new contact to show up in one of the pull-down lists, click the "General Contacts" tab.

Environmental:	<input type="radio"/> Bond, James - Brits Intell	<input type="radio"/> Unknown for now
Civil:	<input type="radio"/> Hoffs, Jimmy - Site Concrete	<input type="radio"/> Unknown for now
Geotechnical:	<input type="radio"/> Quest John - Quest Engineering	<input type="radio"/> Unknown for now
Structural:	<input type="radio"/> Ripper, Jack - Cutting Edge Technologies	<input type="radio"/> Unknown for now
Land Developer:	<input type="radio"/> Tracy, Dick - Tracy Investigations	<input type="radio"/> Unknown for now
Site Development:	<input type="radio"/> Bryant John - Bryant Consultants	<input type="radio"/> Unknown for now

Save Contact Information

804 802 814 800 312 314

FIG 8  
 Project Contacts Screen





306

Geoneering.com Site Development Questionnaire - Microsoft Internet Explorer

http://sitedevelopment.geoneering.com/e/geoneering.html?tab=Civil&stateInfo=aLHC&tabId=Yq8833|14

# BRYANT

CONSULTANTS

Geoneering [PROJECT ADMIN] [CONTACT ADMIN] [GEONEERING OVERVIEW] [LOG OUT]

Project: Swampland Estates Phase I [U]

Risks Civil Site Development Environmental Geotechnical Structural

Have you participated in an early development/pre-construction meeting to evaluate potential civil/site challenges? More Info

1006 ☒ Yes 1006 ☒ No

1010 ☒ Don't Know 1012 ☒ Skip for now 1004

Has the civil engineer provided positive grades on each of the building lots? More Info

1006 ☒ Yes 1008 ☒ No

1010 ☒ Don't Know 1012 ☒ Skip for now

Has sufficient pad design been done to avoid excessive cut and fill beneath the building pads? More Info

1006 ☒ Yes 1008 ☒ No

1010 ☒ Don't Know 1012 ☒ Skip for now

310  
312  
314  
1000

FIG 10

Civil Screen




FIG 11  
Geoneering Overview




FIG. 12  
Administrative Main Menu  
Screen




FIG 13  
Setting Screen

Site Administration - Microsoft Internet Explorer

http://sitedevelopment.geoneering.com/e/mt\_settings.html?rowid=0x00005d80&stateInfo=elHCEJrac8BdaJYq8833|25

# BRYANT

CONSULTANTS

Maintain System Settings [ADMIN MAIN MENU] [LOG OUT]

Account ID:  ID Type:  All

Setting Type:  General

Setting Name:  SessionTimeoutPeriod

Setting Value:  3600

Setting Description: Number of seconds to keep a web user's session active while waiting for a response from them. If the user simply goes away without hitting the site for too long, their session will be

Account Info:  00/24/00 15:12:45 Feb 00/00/00

Updated: 11/04/02 12:50:24

[ADMIN MAIN MENU] [LOG OUT]

Done

FIG 14  
Edit a Setting Screen




FIG 15  
Maintain Client Screen




FIG 16  
Edit client screen






FIG 17  
Maintain User Ssr

Site Administration - Microsoft Internet Explorer

http://skeddevelopment.geoneering.com/e/mt\_skeusers.html?rowid=0x0000ec62&stateInfo=elHcEltac8bdaYq6833|32

# BRYANT

CONSULTANTS

Maintain System Users [ADMIN MAIN MENU] [LOG OUT]

User ID: 17 (Automatically assigned)

User Name: demo

Password: qhbaenldxdkMyYc (encoded, not actual password)

Start Date: ? (MM/DD/YY)

End Date: ? (MM/DD/YY)

Admin User: ☐ (Check this box to make the user an admin user)

Client: B-Demo [Maintain Client List]

Failure Count: 0 (Reset to zero if user is locked out)

Phone:

[Submit] [Delete]

[Print] [Refresh]

[ADMIN MAIN MENU] [LOG OUT]

FIG 18  
Specific User Screen

Site Administration - Microsoft Internet Explorer

Address: http://sitedevelopment.geonsering.com/e/brws\_questions.html?stateInfo=eLHcEjracBbdaJYq8833|35

# BRYANT

CONSULTANTS

Maintain Questions [ADMIN MAIN MENU] [LOG OUT]

Showing Items 1 - 10 of 32 1 2 3 4 [Next]

ID	Area	Sort	Text	ActionURL
1	37 C	0	Have you participated in an early development pre-construction meeting to evaluate potential civil site challenges?	More Info
2	19 C	2	Has the civil engineer provided positive grades on each of the building lots?	More Info
3	20 C	1	Has sufficient pad design been done to avoid excessive cut and fill beneath the building pads?	More Info
4	21 C	6	Has the erosion control been addressed in the civil engineering report?	More Info
5	22 C	8	Has retaining structures been identified for this site?	More Info
6	23 C	10	Has civil engineer provided control of surface and subsurface water migration, if the potential exists?	More Info
7	24 C	12	Have the final grades and drainage been validated as specified in the civil engineering design document?	More Info
8	29 D	0	Does the tree canopy extend over building site pad?	More Info

Maintain screen  
2400

1802

314

2404

2404

2404

2404

2404

2404

2404

2404

2402

FIG 19

Maintain Questions

Site Administration - Microsoft Internet Explorer

http://sitedevelopment.geoneering.com/e/mt\_questions.html?rowid=0x0000e0a0&stateInfo=eLHcEjxc8bdaJYq6833|36

# BRYANT

CONSULTANTS

Maintain Questions [ADMIN MAIN MENU] [LOG OUT]

Question ID: 2533 automatically was generated

Question Area: Civil

Sort Order: 0

Question Text: Have you participated in an early development, pre-construction meeting to evaluate potential civil site challenges?

Action URL: <a href="/overview.html" target="new">More Info</a>

Risks: Yes: 0 No: 102 Skip: 0 DK: 103

Executable: procs/mailto.p

Submit Delete Audit Info

Created: 11/12/02 09:24:25 2

Updated: 11/12/02 09:25:10 2

[ADMIN MAIN MENU] [LOG OUT]

FIG 20 ,  
Maintain Specific  
Question Screen

Site Administration - Microsoft Internet Explorer

Address: http://sitedevelopment.geoneering.com/ej/bwrs\_risks.html?stateInfo=eLHCEJtacBbdaJYq8833|38

# BRYANT

CONSULTANTS

Maintain Risks

[ADMIN MAIN MENU] [LOG OUT]

Showing Items 1 - 10 of 54

ID	Area	Sort	Text	ActionURL
102	C	0	Setup up a meeting with all interested parties on civil engineering site challenges.	
103	C	2	Meeting needed to reduce information gaps, communicate process, and reduce risk.	
104	C	4	Contact your land developer about positive grades on each of the building lots.	
105	C	6	Determine grade requirements for this site, BCI recommend 2% grade eight feet from the perimeter of a structure.	<a href="#">More Info</a>
106	C	8	Contact land developer regarding higher risk involved with excessive cut and fill.	
107	C	10	Review cut and fill information.	<a href="#">More Info</a>
108	C	12	Contact civil engineer for an erosion control recommendation.	
109	C	14	Review civil engineer report for erosion control recommendations.	

1802  
maintain risks screen  
2600

314

2611

2613

2616 2618 2620

2622

2624

FIG 21  
Maintain Risks  
screen

Site Administration - Microsoft Internet Explorer

http://skeddevelopment.geocneering.com/mt\_risks.html?rowid=0x00005fe4&stateInfo=eLHcEjtc8bdaYq8833|39

# BRYANT

CONSULTANTS

## Maintain Risks

[ADMIN MAIN MENU] [LOG OUT]

Risk ID:	102 (Automatically assigned)
Risk Area:	Civil
Sort ID:	0 (Within the area selected)
Risk Text:	Setup up a meeting with all interested parties on civil engineering site challenges
Action URL:	
Distributing list:	ECGSLO

Submit Cancel Audit Item

Created: 11/20/02 07:39:18  
Updated: 7/02/04 (Audit fields are automatically maintained.)

[ADMIN MAIN MENU] [LOG OUT]

maint file  
2700

1802

314

2714

2716

2718

1700

2722

2724

2706

2710

2708

2712

FIG 22

specific risk screen




FIG 23  
Maintain Contact  
Screen

Site Administration - Microsoft Internet Explorer

http://sitedevelopment.geoneering.com/e/mt\_contacts.html?rowId=0x000060e68.stateInfo=eLHCeJtacBbdaJYq8833|42

# BRYANT

CONSULTANTS

Maintain System Contacts

[ADMIN MAIN MENU] [LOG OUT]

Contact ID:	16 (Automatically assigned)	
Client:	8-Demo	<input checked="" type="checkbox"/> Maintain Client Data
Last Name:	Bryant	
First Name:	John	
Company:	Bryant Consultants	
Email:	jbryant@geoneering.com	
Phone:	666-666-6666	

Submit	Save	Cancel
Back to Main Contacts	Advanced Info	Created: 08/29/02 11:16:27 AM
	Updated:	

2906 2910 2908

[ADMIN MAIN MENU] [LOG OUT]

Maintain System Contacts  
2900

1802  
314

2912  
2914  
2916  
2918  
2920

FIG 24  
Specific Contact  
Screen



Site Administration - Microsoft Internet Explorer

http://sitedevelopment.geoneering.com/e/brows\_eventlogs.html

# BRYANT

CONSULTANTS

System Events [ADMIN MAIN MENU] [LOG OUT]

Starting: 10/27/02  
Ending: 11/26/02  
[Show Events](#)

ID	Date	Time	Event	User ID	Client ID
253	11/11/02	09:55:58	Login Failure: User demo1	0	0
254	11/11/02	09:56:09	Login Failure: User demo1	0	0
255	11/11/02	09:56:28	Login Failure: User demo1	0	0
256	11/11/02	09:56:39	Login Failure: User kzjones	0	0
257	11/11/02	09:56:52	Login Failure: User kzj	0	0
258	11/11/02	09:57:18	Login Failure: User kzj	0	0
259	11/11/02	09:57:54	Login Failure: User kzjones	0	0
260	11/11/02	09:59:28	Login Failure: User kzj	0	0
261	11/11/02	10:12:51	Login: User kzj	2	4
262	11/11/02	10:13:10	Login: User kzj	2	4
263	11/11/02	10:14:01	Login: User demo1	15	8
264	11/11/02	10:14:25	Login: User demo1	15	8
265	11/11/02	10:15:08	Login: User demo1	15	8

3002

314

3000

3002

3004

3006

3008

3010

3011

3012

3014

3016

How does this page work?

FIG 25  
System Events




FIG 26  
Session and hit  
tracking screen





FIG 27  
Session Screen

Site Administration - Microsoft Internet Explorer

Address: http://sitedevelopment.geoneering.com/e/sessiontrace.html?sessionId=eLHcEjtacBbdajYq8833&stateInfo=eLHcEjtacBbdajYq8833|59

Hit #	Date & Time	Object Run	Query	Cookie
1	11/26/02 10:37:00	signup	GET	valuedGuest=Yes 010
2	11/26/02 10:37:50	login	GET: stateInfo=eLHcEjtacBbdajYq8833 1	valuedGuest=Yes 010 safeSessionID=eLHcEjtacBbdajYq8833 1
3	11/26/02 10:38:07	signup	GET	valuedGuest=Yes 010 safeSessionID=eLHcEjtacBbdajYq8833 1
4	11/26/02 10:38:57	login	GET: stateInfo=eLHcEjtacBbdajYq8833 3	valuedGuest=Yes 010 safeSessionID=eLHcEjtacBbdajYq8833 3
5	11/26/02 10:39:29	login	POST: stateInfo=eLHcEjtacBbdajYq8833 4 adminUser=demo password=demo runAction=logIn	valuedGuest=Yes 010 safeSessionID=eLHcEjtacBbdajYq8833 4
6	11/26/02 10:39:29	project	GET: stateInfo=eLHcEjtacBbdajYq8833 5	valuedGuest=Yes 010 safeSessionID=eLHcEjtacBbdajYq8833 5
7	11/26/02 10:39:59	projectadmin	GET: stateInfo=eLHcEjtacBbdajYq8833 6	valuedGuest=Yes 010 safeSessionID=eLHcEjtacBbdajYq8833 6
8	11/26/02 10:40:35	mt_projects	GET: mode=edit projectID=56 stateInfo=eLHcEjtacBbdajYq8833 7	valuedGuest=Yes 010 safeSessionID=eLHcEjtacBbdajYq8833 7
9	11/26/02	projectadmin	GET	valuedGuest=Yes 010

FIG 28  
Hit tracking  
screen



To Fig. 36B

Figure 29A




Figure 29B




Figure 30




Figure 31